



DETAIL B  
SCALE 1 : 1



1. Install a mounting rail DIN50 EN50022 (if not existing) on the wall.
2. Mount the JB70D2-SA on the rail (Be sure that the unit is properly mounted, see detail B)
3. Mark the 4 centerpoints for the drill in the wall.  
NB! The drilling holes diam. depends on thickness and material of the wall.
4. Use self tapping screws ST3,5 DIN7981-C pozidrive (A) (The screw length depends on the wall thickness).

CN	xx-xxx xx Date								
Designed by - date	A.Matre 2014.05.27	Checked by	XXX	Approved by - date	XXX	Material	XXX		
						Name	JB70D21 mounted on wall		
						Drwg. no.	XXX	Revision	XX
Gen. tolerance	ISO2768m	Eur. projection		Scale	X:X	Edition date	YYYY.MM.DD	Sheet	X of X