

Technical data:

Remarks:

The valve housing has been subjected to a hydrostatic pressure test, and the valve assembly to a seat leakage test to 5 bar. Holding time 5 minutes.

Marking and certificate numbers for the different parts:

Drawings with dates of approval and/or type approval certificate number:
DNV S-6000